

The A5025 south of Pentraeth.

The decision to drastically reduce the length of the overtaking zone is the primary cause of this 'near miss'. We need to know who made it and why?

The ARRIVE ALIVE Vans drive this route almost daily, they would ignore this incident as their drivers have NO INTEREST in real road safety issues!



In this shot the Quad bike crosses the double lines into the Farmyard. This bike was apparently unregistered with no lights or indicators and was the cause of two high risk incidents.

The shot below shows the end of the double line in the 'dip' and much closer to the blind bend.

At no time were any of the vehicles exceeding 40 mph on this 60 mph limited section.



Ahead we can see the third car overtaking the Farmer's Quad bike. This car was on the double lines before returning to the left lane.



This shot shows the extended double line from the brow of the hill, the previous end point and the clearest view of the road ahead.