


" PPP "

People for Proper Policing in North Wales

**The approaches to the Pen
tunnel going East on the A55**



These shots show what the drivers see suddenly when coming round the bend to the tunnel at 50 mph, two 30 signs and a camera (circled). What is the purpose/status of these signs? they are VERY misleading on a route carrying MULTI-NATIONAL traffic.

The double lines on this whole section are non-standard width and spacing.....what is the purpose/status of these?.

**After a private meeting with an NWPF traffic Officer the 30 signs were removed as were the 50 limit signs before the 1st tunnel. We were informed that the unusual lines were for when a contro flow was in use and could be crossed normally.
A very useful meeting!**